

Sample: a made-up car and made-up shops. Your estimate will be about your car.

Rivet

EEAB Studio Limited LLC

Preliminary repair estimate

Estimate No. RV-2026-000000

Issued September 22, 2026 at 12:00 PM

Valid until September 24, 2026 at 12:00 PM

Vehicle

Nissan Patrol Y62 2019

VIN

JN8AY2NF5K9350111

#	Part number	Description · Shop	Condition	Qty	Unit price	Amount
1	62022-1LB0H	Front bumper cover Confirmed Al Nasr Auto Parts · 14 d	Aftermarket, new	1	AED 1,320.00	AED 1,320.00
2	26060-6JL0A	Headlight, left Confirmed Gulf Optics · 3 d · *	Genuine, new	1	AED 7,450.00	AED 7,450.00
3	62030-1LA0A	Front bumper reinforcement Likely Souq Al Haraj — Rashid · 1 d	Aftermarket, new	1	AED 580.00	AED 580.00
4	01553-09321	BUMPER CLIP Confirmed Al Nasr Auto Parts · 0 d Shop has 8 of 12	Aftermarket, new	12	AED 15.00	AED 180.00

* The shop will confirm this price before ordering

Parts total

AED 9,530.00

Shop prices. VAT as charged by the shop.

Parts without a price

No shop has quoted these yet. They are not included in the total.

AC condenser · 92100-1LA0A

× 1 Likely

Labour and procedures

Priced by the workshop. Not included in the total.

Repair and paint: Front fender, left

Wheel alignment

Not visible in the photos

Check these at the workshop: they can change the estimate.

Airbags

Frame rails

This is an estimate based on photos, not an expert assessment. Rivet is not a seller: the shop is responsible for the part, its quality, warranty and returns.

Body repair in the UAE requires a police report.

EEAB Studio Limited LLC · Masdar City, Abu Dhabi, United Arab Emirates

SAMPLE